



## VB

### SEMPLICE EFFETTO MAGNETICO - SINGLE-ACTING MAGNETIC

| Ø mm. | A  | B  | D   | E   | F  | G    | L   | R    | AM | BG | EE    | KK       | SW | VA | VD | WH |
|-------|----|----|-----|-----|----|------|-----|------|----|----|-------|----------|----|----|----|----|
| 32    | 12 | 30 | M6  | 47  | 48 | 28   | 119 | 32,5 | 22 | 16 | 1/8G. | M10x1,25 | 10 | 4  | 20 | 26 |
| 40    | 16 | 35 | M6  | 53  | 54 | 31,5 | 130 | 38   | 24 | 16 | 1/4G. | M12x1,25 | 13 | 4  | 22 | 30 |
| 50    | 20 | 40 | M8  | 65  | 69 | 31,5 | 131 | 46,5 | 32 | 16 | 1/4G. | M16x1,5  | 17 | 4  | 28 | 37 |
| 63    | 20 | 45 | M8  | 75  | 69 | 35   | 146 | 56,5 | 32 | 16 | 3/8G. | M16x1,5  | 17 | 4  | 28 | 37 |
| 80    | 25 | 45 | M10 | 95  | 86 | 36   | 153 | 72   | 40 | 16 | 3/8G. | M20x1,5  | 22 | 4  | 34 | 46 |
| 100   | 25 | 55 | M10 | 115 | 91 | 41   | 163 | 89   | 40 | 16 | 1/2G. | M20x1,5  | 22 | 4  | 38 | 51 |